Project No.: : ERI 2002: Former Exxon Sensite: : 6301 Commerce Boulevard, Logged By: : Paula Sime Reviewed By: : John B. Bobbar G 3 3 Signature:					er Exx				: 07/20/05 and 7/21/05 : Gregg Drilling Company : Direct-Push : Hand Auger/Continuous : 6*/2* : N/A : : 20' bgs : 9.31' bgs	
Depth (ft)	Blow Count	OVM/PID (ppmv)	Sample	Column	USCS	Sample Condition No Recovery Sampled Interval Described Sample Preserved Sample DESCRIPTION Water Levels W GW first encountered at 9			Boring: B13	
0-		1.1				Elevated planter with grass surface. (air/water knife, and vacuum excavatic ground surface. SILTY SAND: fine-grained, medium o graded, trace coarse-grained sand, ro SANDY CLAY WITH GRAVEL: dark high plasticity, roots present, hard, sa and subangular	orange brown, dry toots, very hard	o damp, poorly		
5— 10—		6.0			CL	6.5 ft: as above; mottled with light gra	WITH SAND: medium grayish brown, damp, medium ck mottling, sand is fine-grained WITH CLAY: fine- to coarse-grained, medium orange d with greenish gray, moist, well graded, trace gravel up imeter T WITH SAND: light olive gray mottled with greenish gray,			
	4				SM ML	brown mottled with greenish gray, mo to 5mm in diameter CLAYEY SILT WITH SAND: light oli moist			Grout	-Grout
	1					13 ft: as above; color change to dark gray SILTY CLAY: mottled orange brown and grayish green, moist, high plasticity, stiff, stringers of black surrounded by greenish gray 16 ft: as above; color change to orange brown SILTY SAND WITH CLAY: fine- to coarse-grained, brown, moist, well graded SAND: dark olive, wet, well graded				
08-30-2005 J/2002/BORING LOGS/B13-bot	1				SM					